30
 Irving Ln., Orinda CA 94563
 9/10/2008
 4536

 BUILDING NO.
 STREET, CITY, STATE, ZIP
 INSPECTION DATE
 REPORT NO.

45360101.jpg


1A



Damage to wall in lower rear bedroom, near vent. Treat and repair.

45360103.jpg

1B



Gap under wall in rear of kitchen. Repair.

45360105.jpg

1C



Gap in wood siding, side of house near laundry room. Repair.